

Case Study:

767 5th Avenue

GM Building

Objective:

- Increase awareness of potential safety hazards
- Enhance safety program to address those hazards

Target:

- Perform monthly and quarterly inspections to assess conditions in the field.
- Enhance communication between employees and management to improve safety environment.
- Ensure safety program objectives are being achieved.

Results:

- Inspections clarified areas where improvement was needed.
- Addressing safety concerns at the location reduced number of incidents.
- Communication between employees and management improved.

